

March 03rd, 2011

Subject: Power On procedure on GT864 terminals

Dear Telit Partners,

the following notice involves the Power On procedure for the following devices:

<i>Product</i>	<i>Part Number</i>
GT864-QUAD	4990150069
GT864-PY	4990150070

Power On procedure

These devices can be found on the field with two different hardware revisions each, having two different behaviors for switching them on.

The hardware revision is printed on the device label.

- On **Rev.E1**, once the Power is applied, it is mandatory to activate high the DTR control line on the RS232 for at least 0.2 seconds.
- On **Rev.B1**, once the Power is applied, it is not needed to activate high the DTR control line on the RS232 for at least 0.2 seconds.

If you have further question regarding integrating these products into your application or for any additional information regarding this notice, please refer to Telit documentation or contact Telit Technical Support Center (TTSC) at TS-EMEA@telit.com.

Best regards,

EMEA Product Management